

**Flood Control Project Maintenance
Levee Inspections**

Fall 2010 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD0010	Not Inspected; 2009 Data	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0010 Honcut		A	21.93				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.44		0.44	2.01%		
Trim / Thin Trees		0.04		0.04	0.18%		
Encroachments		0.03		0.03	0.14%	0.01	
Animal Control		0.08		0.08	0.37%		
<i>LMA Totals:</i>		0.59	0.00	0.59	2.69%	0.01	0.00
Unit No. 01 Simmerly Slough		Overall Unit Rating	Total Unit Miles				
RD0010	Not Inspected; 2009 Data	A	7.68				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.05		0.05	0.65%		
Trim / Thin Trees		0.02		0.02	0.26%		
<i>Unit Totals:</i>		0.07	0.00	0.07	0.91%	0.00	0.00
Unit No. 02 Feather River		Overall Unit Rating	Total Unit Miles				
RD0010	Not Inspected; 2009 Data	A	11.24				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.38		0.38	3.38%		
Trim / Thin Trees		0.01		0.01	0.09%		
Encroachments		0.03		0.03	0.27%	0.01	
Animal Control		0.07		0.07	0.62%		
<i>Unit Totals:</i>		0.49	0.00	0.49	4.36%	0.01	0.00
Unit No. 03 Honcut Creek		Overall Unit Rating	Total Unit Miles				
RD0010	Not Inspected; 2009 Data	A	3.01				
Rated Item		M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
						PO Miles	CO Miles
<i>Earthen Levee</i>							
Vegetation		0.01		0.01	0.33%		
Trim / Thin Trees		0.01		0.01	0.33%		
Animal Control		0.01		0.01	0.33%		
<i>Unit Totals:</i>		0.03	0.00	0.03	1.00%	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2010 Levee Inspection Results

Reclamation District No. 0010 Honcut

	Spring (March - May)	Summer ** (June - August)	Fall (2009) (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

>> Due to resourcing challenges, this District did not have inspections completed for Fall 2010. <<

**Data from the Fall 2009 inspection was used for summary purposes.
For detailed data, see the Fall 2009 Detail Levee Inspection Report.**

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2010 Levee Inspection Results

Reclamation District No. 0010 Honcut

Waterway			Bank	Unit Miles
Unit No. 01 Simmerly Slough			Right	7.68
	Spring (2010) (March - May)	Summer (June - August)	Fall (2009) (September - November)	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/15/2010 - 4/15/2010		10/29/2009 - 10/29/2009	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Finlay Williams		Finlay Williams	

>> Due to resourcing challenges, this District did not have inspections completed for Fall 2010. <<
Data from the Fall 2009 inspection was used for summary purposes.
For detailed data, see the Fall 2009 Detail Levee Inspection Report.

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Suite 200
 Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2010 Levee Inspection Results

Reclamation District No. 0010 Honcut

Waterway			Bank	Unit Miles
Unit No. 02 Feather River			Left	11.24
	Spring (2010) (March - May)	Summer (June - August)	Fall (2009) (September - November)	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/15/2010 - 4/15/2010		10/29/2009 - 10/29/2009	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Finlay Williams		Finlay Williams	

>> Due to resourcing challenges, this District did not have inspections completed for Fall 2010. <<
Data from the Fall 2009 inspection was used for summary purposes.
For detailed data, see the Fall 2009 Detail Levee Inspection Report.

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Suite 200
 Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2010 Levee Inspection Results

Reclamation District No. 0010 Honcut

Waterway			Bank	Unit Miles
Unit No. 03 Honcut Creek			Left	3.01
	Spring (2010) (March - May)	Summer (June - August)	Fall (2009) (September - November)	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/15/2010 - 4/15/2010		10/29/2009 - 10/29/2009	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Finlay Williams		Finlay Williams	

>> Due to resourcing challenges, this District did not have inspections completed for Fall 2010. <<
Data from the Fall 2009 inspection was used for summary purposes.
For detailed data, see the Fall 2009 Detail Levee Inspection Report.

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
 3310 El Camino Avenue, Suite 200
 Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date